

Training Office, Bldg. 911A.

[illegible]

<p>Spill, Release, Breakage Clean-up Plan (Describe possible release scenario and action, including clean-up worker training, exposure monitoring, personal protective equipment, and disposal):</p> <p>Will call ES&H</p>	
<p>Pollution Prevention Plan: (Describe pollution prevention and waste minimization measures):</p> <p>Will dispose of properly after experiment is over.</p>	
<p>End of Project Plan: (Describe the actions when the use of beryllium is no longer needed, including accounting for material consumption and funding of disposal):</p> <p>No consumption. Will dispose of properly at end of experiment. (either recycle or hazardous waste).</p>	
<p>Completed by: Steve Kettell</p>	<p>Date: 3/21/01</p>
<p>Reviewed by: Lori Stiegler</p>	<p>Date: 3/22/01</p>
<p>Approved by: Lori Stiegler</p>	<p>Date: 3/22/01</p>